**BRUHAT BANGALORE MAHANAGARA PALIKE**

# MEASUREMENT SHEET

## RA 1ST AND FINAL BILL

Name of work: Emergency Works inclduing Filling of Potholes, Desilting of Drains and Providing Missing Covering Slabs in ward No. 11, (Kuvempunagara) in Vidyaranyapura Sub Division.

Estimated Cost : Rs. 30.00 Lakhs

Head of Account : P-1771

Job Code: 011-18-000079

Name of Agency: Sri. A. Puttaraju, Contractor, # 48/5, Pipeline B Cross, Bhabalinagara, Jalahalli, Bangalore – 560 013.

Work order No: BBMP/EE/BTP/WO/99/2018-19 D: 31.08.2018.

Measurements Recarded on :

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| 1 | Providing, laying, spreading and compacting crushed stone aggregates of granite / trap / basalt to wet mix macadam specifications including pre mixing the material with water at OMC in mechanical mix plant carriage of mixed method of tipper to site, laying in uniform layers with paver in sub-base/base course on well prepared surface and compacting with vibratory roller to achieve the desired density complete as per specificationss | | | | | | | | Cum | |
| | Singapura Main Road | 1 | 1.50 | | | 1.50 | 0.15 | 0.34 | | |
| | | 1 | 1.35 | | | 1.80 | 0.15 | 0.36 | | |
| | | 1 | 2.10 | | | 1.95 | 0.15 | 0.61 | | |
| | | 1 | 1.30 | | | 1.25 | 0.15 | 0.24 | | |
| | | 2 | 1.40 | | | 1.30 | 0.15 | 0.55 | | |
| | | 1 | 1.00 | | | 1.00 | 0.15 | 0.15 | | |
| | Singapura 1st Cross | 1 | 12.00 | | | 2.50 | 0.15 | 4.50 | | |
| | | 1 | 2.20 | | | 3.00 | 0.15 | 0.99 | | |
| | | 3 | 3.00 | | | 2.00 | 0.15 | 2.70 | | |
| | | 1 | 1.80 | | | 1.80 | 0.15 | 0.49 | | |
| | | 2 | 2.20 | | | 3.00 | 0.15 | 1.98 | | |
| | | 1 | 2.50 | | | 3.90 | 0.15 | 1.46 | | |
| | | 1 | 1.20 | | | 1.30 | 0.15 | 0.23 | | |
| | | 4 | 1.10 | | | 2.00 | 0.15 | 1.32 | | |
| | Singapura 3rd Cross | 1 | 1.00 | | | 1.00 | 0.15 | 0.15 | | |
| | | 2 | 4.00 | | | 1.20 | 0.15 | 1.44 | | |
| | | 1 | 1.00 | | | 0.90 | 0.15 | 0.14 | | |
| | | 1 | 5.50 | | | 0.90 | 0.15 | 0.74 | | |
| | | 1 | 5.50 | | | 0.60 | 0.15 | 0.50 | | |
| | | 2 | 2.00 | | | 1.20 | 0.15 | 0.72 | | |
| | | 1 | 5.50 | | | 0.90 | 0.15 | 0.74 | | |
| | Singapura Layout Main Road | 1 | 1.20 | | | 1.00 | 0.15 | 0.18 | | |
| | | 1 | 1.00 | | | 1.00 | 0.15 | 0.15 | | |
| | | 2 | 1.00 | | | 1.00 | 0.15 | 0.30 | | |
| | | 1 | 1.50 | | | 1.20 | 0.15 | 0.27 | | |
| | | 1 | 1.40 | | | 1.00 | 0.15 | 0.21 | | |
| | | 3 | 1.30 | | | 1.50 | 0.15 | 0.88 | | |
| | | 1 | 1.60 | | | 1.20 | 0.15 | 0.29 | | |

Assistant Engineer

Assistant Executive Engineer

Assistant Executive Engineer
Vidyaranyapura Sub Division

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| | | 1 | 2.40 | | | 1.30 | 0.15 | 0.47 | | |
| | Singapura Layout 1st Main | 1 | 1.80 | | | 1.60 | 0.15 | 0.43 | | |
| | | 4 | 1.30 | | | 1.80 | 0.15 | 1.40 | | |
| | | 1 | 1.35 | | | 1.80 | 0.15 | 0.36 | | |
| | | 1 | 2.10 | | | 1.95 | 0.15 | 0.61 | | |
| | | 2 | 1.30 | | | 1.25 | 0.15 | 0.49 | | |
| | | 1 | 5.50 | | | 0.90 | 0.15 | 0.74 | | |
| | | 1 | 5.50 | | | 0.90 | 0.15 | 0.74 | | |
| | | 1 | 2.10 | | | 2.00 | 0.15 | 0.63 | | |
| | Singapura Layout 1st Main 1st Cross | 1 | 1.40 | | | 1.00 | 0.15 | 0.21 | | |
| | | 1 | 1.30 | | | 1.50 | 0.15 | 0.29 | | |
| | | 3 | 1.40 | | | 1.30 | 0.15 | 0.82 | | |
| | | 1 | 1.50 | | | 1.20 | 0.15 | 0.27 | | |
| | | 1 | 1.40 | | | 1.00 | 0.15 | 0.21 | | |
| | | 1 | 1.30 | | | 1.50 | 0.15 | 0.29 | | |
| | | 2 | 1.60 | | | 1.20 | 0.15 | 0.58 | | |
| | | 1 | 2.40 | | | 1.30 | 0.15 | 0.47 | | |
| | | 1 | 1.20 | | | 2.80 | 0.15 | 0.50 | | |
| | Singapura Layout 1st Main 2nd Cross | 1 | 1.80 | | | 1.40 | 0.15 | 0.38 | | |
| | | 1 | 2.20 | | | 1.60 | 0.15 | 0.53 | | |
| | | 3 | 3.20 | | | 2.20 | 0.15 | 3.17 | | |
| | | 1 | 1.80 | | | 1.80 | 0.15 | 0.49 | | |
| | | 1 | 2.20 | | | 1.30 | 0.15 | 0.43 | | |
| | | 1 | 2.50 | | | 3.90 | 0.15 | 1.46 | | |
| | | 2 | 1.20 | | | 1.20 | 0.15 | 0.43 | | |
| | | 1 | 1.10 | | | 2.60 | 0.15 | 0.43 | | |
| | | 1 | 1.50 | | | 2.10 | 0.15 | 0.47 | | |
| | | 1 | 4.30 | | | 1.50 | 0.15 | 0.97 | | |
| | Singapura Layout 2nd Main | 2 | 2.20 | | | 1.80 | 0.15 | 1.19 | | |
| | | 1 | 1.60 | | | 1.70 | 0.15 | 0.41 | | |
| | | 1 | 1.60 | | | 1.40 | 0.15 | 0.34 | | |
| | | 1 | 1.20 | | | 2.20 | 0.15 | 0.40 | | |
| | | 3 | 1.50 | | | 1.50 | 0.15 | 1.01 | | |
| | | 1 | 1.80 | | | 1.40 | 0.15 | 0.38 | | |
| | | 1 | 2.10 | | | 2.50 | 0.15 | 0.79 | | |
| | | 1 | 1.20 | | | 2.60 | 0.15 | 0.47 | | |
| | Singapura Layout 1st Cross | 1 | 1.50 | | | 1.90 | 0.15 | 0.43 | | |
| | | 1 | 1.70 | | | 1.60 | 0.15 | 0.41 | | |
| | | 1 | 1.25 | | | 1.10 | 0.15 | 0.21 | | |
| | | 4 | 4.50 | | | 0.90 | 0.15 | 2.43 | | |
| | | 1 | 1.50 | | | 1.60 | 0.15 | 0.36 | | |
| | | 1 | 2.50 | | | 1.80 | 0.15 | 0.68 | | |
| | | 2 | 1.80 | | | 1.40 | 0.15 | 0.76 | | |
| | | 1 | 6.00 | | | 1.50 | 0.15 | 1.35 | | |
| | Singapura Layout 2nd Cross | 1 | 2.20 | | | 1.30 | 0.15 | 0.43 | | |
| | | 3 | 1.60 | | | 1.80 | 0.15 | 1.30 | | |
| | | 1 | 4.00 | | | 3.00 | 0.15 | 1.80 | | |
| | | 1 | 1.00 | | | 1.00 | 0.15 | 0.15 | | |
| | | 4 | 3.50 | | | 2.80 | 0.15 | 5.88 | | |
| | | 1 | 3.00 | | | 2.20 | 0.15 | 0.99 | | |
| | | 1 | 1.80 | | | 2.50 | 0.15 | 0.68 | | |

Assistant Engineer

Assistant Executive Engineer

Assistant Executive Engineer
Sub Division

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| | | 2 | 6.00 | | | 3.40 | 0.15 | 6.12 | | |
| | Singapura Layout 3rd Cross | 1 | 2.60 | | | 2.80 | 0.15 | 1.09 | | |
| | | 1 | 4.60 | | | 2.10 | 0.15 | 1.45 | | |
| | | 3 | 1.00 | | | 1.50 | 0.15 | 0.68 | | |
| | | 1 | 4.70 | | | 0.90 | 0.15 | 0.63 | | |
| | Kuvempunagara 1st Stage | 1 | 12.50 | | | 2.50 | 0.15 | 4.69 | | |
| | Samudhaya Bhavan Road | 4 | 1.80 | | | 2.00 | 0.15 | 2.16 | | |
| | | 1 | 0.90 | | | 0.60 | 0.15 | 0.08 | | |
| | | 2 | 1.10 | | | 1.50 | 0.15 | 0.50 | | |
| | | 1 | 5.20 | | | 3.50 | 0.15 | 2.73 | | |
| | | 1 | 5.20 | | | 0.90 | 0.15 | 0.70 | | |
| | | 1 | 3.80 | | | 2.00 | 0.15 | 1.14 | | |
| | | 3 | 5.40 | | | 1.20 | 0.15 | 2.92 | | |
| | | 1 | 6.00 | | | 2.50 | 0.15 | 2.25 | | |
| | | 1 | 1.80 | | | 1.40 | 0.15 | 0.38 | | |
| | | 1 | 2.10 | | | 3.20 | 0.15 | 1.01 | | |
| | Kuvempunagara 1st Stage Cross Road | 4 | 1.20 | | | 2.60 | 0.15 | 1.87 | | |
| | | 1 | 1.50 | | | 1.90 | 0.15 | 0.43 | | |
| | | 1 | 1.70 | | | 1.60 | 0.15 | 0.41 | | |
| | | 1 | 1.25 | | | 1.10 | 0.15 | 0.21 | | |
| | | 1 | 4.50 | | | 0.90 | 0.15 | 0.61 | | |
| | | 3 | 1.50 | | | 1.60 | 0.15 | 1.08 | | |
| | | 1 | 2.50 | | | 1.80 | 0.15 | 0.68 | | |
| | | 1 | 1.80 | | | 1.40 | 0.15 | 0.38 | | |
| | Kuvempunagara 1st Stage Cross Road | 1 | 6.00 | | | 1.50 | 0.15 | 1.35 | | |
| | | 1 | 2.20 | | | 1.30 | 0.15 | 0.43 | | |
| | | 2 | 2.50 | | | 3.90 | 0.15 | 2.93 | | |
| | | 1 | 1.20 | | | 1.30 | 0.15 | 0.23 | | |
| | | 1 | 1.10 | | | 1.20 | 0.15 | 0.20 | | |
| | | 1 | 1.50 | | | 2.10 | 0.15 | 0.47 | | |
| | | 4 | 4.30 | | | 1.50 | 0.15 | 3.87 | | |
| | | 1 | 2.20 | | | 1.80 | 0.15 | 0.59 | | |
| | | 1 | 1.60 | | | 1.70 | 0.15 | 0.41 | | |
| | Varadarajanagara main Road | 1 | 1.60 | | | 1.40 | 0.15 | 0.34 | | |
| | | 2 | 1.20 | | | 2.00 | 0.15 | 0.72 | | |
| | | 1 | 1.50 | | | 1.50 | 0.15 | 0.34 | | |
| | | 1 | 1.80 | | | 1.40 | 0.15 | 0.38 | | |
| | | 1 | 2.10 | | | 1.30 | 0.15 | 0.41 | | |
| | | 2 | 1.00 | | | 4.00 | 0.15 | 1.20 | | |
| | | 3 | 4.20 | | | 1.50 | 0.15 | 2.84 | | |
| | 1st Cross Road | 1 | 3.80 | | | 1.00 | 0.15 | 0.57 | | |
| | | 1 | 1.30 | | | 3.50 | 0.15 | 0.68 | | |
| | | 1 | 1.60 | | | 3.50 | 0.15 | 0.84 | | |
| | | 1 | 2.40 | | | 1.30 | 0.15 | 0.47 | | |
| | | 2 | 1.80 | | | 1.60 | 0.15 | 0.86 | | |
| | | 1 | 3.50 | | | 1.80 | 0.15 | 0.95 | | |
| | | 1 | 1.35 | | | 1.80 | 0.15 | 0.36 | | |
| | 2nd Cross | 1 | 2.10 | | | 4.00 | 0.15 | 1.26 | | |
| | | 1 | 1.30 | | | 1.25 | 0.15 | 0.24 | | |
| | | 1 | 5.50 | | | 0.90 | 0.15 | 0.74 | | |
| | | 4 | 5.50 | | | 0.90 | 0.15 | 2.97 | | |

Assistant Engineer

Assistant Executive Engineer

Assistant Executive Engineer
Vidyaranyapura Sub Division

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| | | 1 | 2.10 | | | 2.00 | 0.15 | 0.63 | | |
| | | 1 | 1.40 | | | 3.00 | 0.15 | 0.63 | | |
| | | 3 | 3.20 | | | 2.20 | 0.15 | 3.17 | | |
| | | 1 | 3.20 | | | 1.80 | 0.15 | 0.86 | | |
| | Srinidhi Layout Main Road | 1 | 2.20 | | | 2.80 | 0.15 | 0.92 | | |
| | | 1 | 2.50 | | | 3.90 | 0.15 | 1.46 | | |
| | | 2 | 4.80 | | | 1.30 | 0.15 | 1.87 | | |
| | | 1 | 3.20 | | | 2.80 | 0.15 | 1.34 | | |
| | | 1 | 1.50 | | | 2.10 | 0.15 | 0.47 | | |
| | | 1 | 4.30 | | | 3.50 | 0.15 | 2.26 | | |
| | | 2 | 2.20 | | | 1.80 | 0.15 | 1.19 | | |
| | 1st Cross Road | 1 | 1.60 | | | 1.70 | 0.15 | 0.41 | | |
| | | 1 | 2.50 | | | 1.40 | 0.15 | 0.53 | | |
| | | 1 | 5.50 | | | 0.95 | 0.15 | 0.78 | | |
| | | 3 | 1.50 | | | 1.50 | 0.15 | 1.01 | | |
| | | 1 | 6.00 | | | 1.40 | 0.15 | 1.26 | | |
| | | 1 | 2.10 | | | 1.30 | 0.15 | 0.41 | | |
| | | 1 | 2.80 | | | 2.60 | 0.15 | 1.09 | | |
| | 2nd Cross | 1 | 3.80 | | | 1.90 | 0.15 | 1.08 | | |
| | | 1 | 9.00 | | | 1.60 | 0.15 | 2.16 | | |
| | | 1 | 5.00 | | | 1.10 | 0.15 | 0.83 | | |
| | | 1 | 6.00 | | | 3.00 | 0.15 | 2.70 | | |
| | | 1 | 2.20 | | | 1.30 | 0.15 | 0.43 | | |
| | Balaji Layout 2nd Main | 2 | 2.50 | | | 3.90 | 0.15 | 2.93 | | |
| | | 1 | 1.20 | | | 1.30 | 0.15 | 0.23 | | |
| | | 1 | 5.50 | | | 3.00 | 0.15 | 2.48 | | |
| | | 1 | 1.50 | | | 2.10 | 0.15 | 0.47 | | |
| | | 3 | 4.30 | | | 1.50 | 0.15 | 2.90 | | |
| | | 1 | 2.20 | | | 1.80 | 0.15 | 0.59 | | |
| | | 1 | 4.00 | | | 2.50 | 0.15 | 1.50 | | |
| | | 1 | 1.60 | | | 1.40 | 0.15 | 0.34 | | |
| | 1st Cross Road | 2 | 1.20 | | | 0.95 | 0.15 | 0.34 | | |
| | | 1 | 4.80 | | | 3.60 | 0.15 | 2.59 | | |
| | | 2 | 1.80 | | | 1.40 | 0.15 | 0.76 | | |
| | | 1 | 2.10 | | | 3.20 | 0.15 | 1.01 | | |
| | | 1 | 4.00 | | | 1.80 | 0.15 | 1.08 | | |
| | | 2 | 2.50 | | | 3.90 | 0.15 | 2.93 | | |
| | | 1 | 2.95 | | | 1.30 | 0.15 | 0.58 | | |
| | 2nd Cross | 1 | 3.00 | | | 2.80 | 0.15 | 1.26 | | |
| | | 1 | 2.80 | | | 2.10 | 0.15 | 0.88 | | |
| | | 4 | 4.30 | | | 1.50 | 0.15 | 3.87 | | |
| | | 1 | 2.20 | | | 1.80 | 0.15 | 0.59 | | |
| | | 1 | 3.20 | | | 1.70 | 0.15 | 0.82 | | |
| | 3rd Cross | 1 | 4.20 | | | 3.00 | 0.15 | 1.89 | | |
| | | 2 | 4.90 | | | 2.00 | 0.15 | 2.94 | | |
| | | 1 | 2.80 | | | 1.50 | 0.15 | 0.63 | | |
| | | 1 | 1.80 | | | 1.40 | 0.15 | 0.38 | | |
| | | 1 | 2.10 | | | 1.30 | 0.15 | 0.41 | | |
| | | 2 | 3.20 | | | 1.60 | 0.15 | 1.54 | | |
| | | 3 | 1.50 | | | 1.20 | 0.15 | 0.81 | | |
| | | | | | | **Total Qty =** | | **188.43** | | |

Assistant Engineer

Assistant Executive Engineer

Assistant Executive Engineer
Sub Division

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | Qty Limited to= | 187.87 | 1768.00 | 332154.00 |
| | | | | | | | | | | |
| 2 | Pot-holes and Patch Repairs with Bituminous Concrete, 40 mm KSRRB M3000-5. Removal of all failed material, trimming of completed excavation to provide firm vertical faces, cleaning of surface, painting of tack coat on the sides and base of excavation as per clause 500.3, filling back the pot holes with hot bituminous material as per clause 500.4, compacting, trimming and finishing the surface to form a smooth continuous surface, all as per clause 3004.2 complete as per specifications | | | | | | | | Sqm | |
| | Singapura Main Road | 1 | 1.50 | | | 1.50 | | 2.25 | | |
| | | 1 | 1.35 | | | 1.80 | | 2.43 | | |
| | | 1 | 2.10 | | | 1.95 | | 4.10 | | |
| | | 1 | 1.30 | | | 1.25 | | 1.63 | | |
| | | 2 | 1.40 | | | 1.30 | | 3.64 | | |
| | | 1 | 1.00 | | | 1.00 | | 1.00 | | |
| | Singapura 1st Cross | 1 | 12.00 | | | 2.50 | | 30.00 | | |
| | | 1 | 2.20 | | | 3.00 | | 6.60 | | |
| | | 3 | 3.00 | | | 2.00 | | 18.00 | | |
| | | 1 | 1.80 | | | 1.80 | | 3.24 | | |
| | | 2 | 2.20 | | | 3.00 | | 13.20 | | |
| | | 1 | 2.50 | | | 3.90 | | 9.75 | | |
| | | 1 | 1.20 | | | 1.30 | | 1.56 | | |
| | | 4 | 1.10 | | | 2.00 | | 8.80 | | |
| | Singapura 3rd Cross | 1 | 1.00 | | | 1.00 | | 1.00 | | |
| | | 2 | 4.00 | | | 1.20 | | 9.60 | | |
| | | 1 | 1.00 | | | 0.90 | | 0.90 | | |
| | | 1 | 5.50 | | | 2.50 | | 13.75 | | |
| | | 1 | 5.50 | | | 2.00 | | 11.00 | | |
| | | 2 | 2.00 | | | 1.20 | | 4.80 | | |
| | | 1 | 5.50 | | | 0.90 | | 4.95 | | |
| | Singapura Layout Main Road | 1 | 1.20 | | | 1.00 | | 1.20 | | |
| | | 1 | 1.00 | | | 1.00 | | 1.00 | | |
| | | 2 | 1.00 | | | 1.00 | | 2.00 | | |
| | | 1 | 1.50 | | | 1.20 | | 1.80 | | |
| | | 1 | 1.40 | | | 1.00 | | 1.40 | | |
| | | 3 | 1.30 | | | 1.50 | | 5.85 | | |
| | | 1 | 1.60 | | | 1.20 | | 1.92 | | |
| | | 1 | 2.40 | | | 1.65 | | 3.96 | | |
| | Singapura Layout 1st Main | 1 | 1.80 | | | 1.60 | | 2.88 | | |
| | | 4 | 1.30 | | | 1.80 | | 9.36 | | |
| | | 1 | 1.35 | | | 1.80 | | 2.43 | | |
| | | 1 | 2.10 | | | 1.95 | | 4.10 | | |
| | | 2 | 1.30 | | | 1.25 | | 3.25 | | |
| | | 1 | 5.50 | | | 0.90 | | 4.95 | | |
| | | 1 | 5.50 | | | 0.90 | | 4.95 | | |
| | | 1 | 2.10 | | | 2.00 | | 4.20 | | |
| | Singapura Layout 1st Main 1st Cross | 1 | 1.40 | | | 1.00 | | 1.40 | | |
| | | 1 | 1.30 | | | 1.50 | | 1.95 | | |
| | | 3 | 1.40 | | | 1.30 | | 5.46 | | |
| | | 1 | 1.50 | | | 1.20 | | 1.80 | | |
| | | 1 | 4.40 | | | 1.80 | | 7.92 | | |
| | | 1 | 1.30 | | | 1.50 | | 1.95 | | |
| | | 2 | 1.60 | | | 1.20 | | 3.84 | | |

Assistant Engineer

Assistant Executive Engineer

Assistant Executive Engineer
Sub Division

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| | | 1 | 2.40 | | | 1.30 | | 3.12 | | |
| | | 1 | 1.20 | | | 2.80 | | 3.36 | | |
| | Singapura Layout 1st Main 2nd Cross | 1 | 1.80 | | | 1.40 | | 2.52 | | |
| | | 1 | 2.20 | | | 1.60 | | 3.52 | | |
| | | 3 | 3.20 | | | 2.20 | | 21.12 | | |
| | | 1 | 1.80 | | | 1.80 | | 3.24 | | |
| | | 1 | 2.20 | | | 1.30 | | 2.86 | | |
| | | 1 | 2.50 | | | 3.90 | | 9.75 | | |
| | | 2 | 1.20 | | | 1.20 | | 2.88 | | |
| | | 1 | 1.10 | | | 2.60 | | 2.86 | | |
| | | 1 | 1.50 | | | 2.10 | | 3.15 | | |
| | | 1 | 4.30 | | | 1.50 | | 6.45 | | |
| | Singapura Layout 2nd Main | 2 | 2.20 | | | 1.80 | | 7.92 | | |
| | | 1 | 1.60 | | | 1.70 | | 2.72 | | |
| | | 1 | 1.60 | | | 1.40 | | 2.24 | | |
| | | 1 | 1.20 | | | 2.20 | | 2.64 | | |
| | | 3 | 1.50 | | | 1.50 | | 6.75 | | |
| | | 1 | 1.80 | | | 1.40 | | 2.52 | | |
| | | 1 | 2.10 | | | 2.50 | | 5.25 | | |
| | | 1 | 1.20 | | | 2.60 | | 3.12 | | |
| | Singapura Layout 1st Cross | 1 | 1.50 | | | 1.90 | | 2.85 | | |
| | | 1 | 1.70 | | | 1.60 | | 2.72 | | |
| | | 1 | 1.25 | | | 1.10 | | 1.38 | | |
| | | 4 | 4.50 | | | 0.90 | | 16.20 | | |
| | | 1 | 3.80 | | | 1.60 | | 6.08 | | |
| | | 1 | 2.50 | | | 1.80 | | 4.50 | | |
| | | 2 | 1.80 | | | 1.40 | | 5.04 | | |
| | | 1 | 6.00 | | | 1.50 | | 9.00 | | |
| | Singapura Layout 2nd Cross | 1 | 2.20 | | | 1.30 | | 2.86 | | |
| | | 3 | 1.60 | | | 1.80 | | 8.64 | | |
| | | 1 | 4.00 | | | 3.00 | | 12.00 | | |
| | | 1 | 2.50 | | | 1.00 | | 2.50 | | |
| | | 4 | 3.50 | | | 2.80 | | 39.20 | | |
| | | 1 | 3.00 | | | 2.20 | | 6.60 | | |
| | | 1 | 3.80 | | | 2.50 | | 9.50 | | |
| | | 2 | 6.00 | | | 3.40 | | 40.80 | | |
| | Singapura Layout 3rd Cross | 1 | 2.60 | | | 2.80 | | 7.28 | | |
| | | 1 | 4.60 | | | 2.10 | | 9.66 | | |
| | | 3 | 1.00 | | | 1.50 | | 4.50 | | |
| | | 1 | 4.70 | | | 0.90 | | 4.23 | | |
| | Kuvempunagara 1st Stage | 1 | 12.50 | | | 2.50 | | 31.25 | | |
| | Samudhaya Bhavan Road | 4 | 1.80 | | | 2.00 | | 14.40 | | |
| | | 1 | 2.60 | | | 0.60 | | 1.56 | | |
| | | 2 | 1.10 | | | 1.50 | | 3.30 | | |
| | | 1 | 5.20 | | | 3.50 | | 18.20 | | |
| | | 1 | 5.20 | | | 0.90 | | 4.68 | | |
| | | 1 | 3.80 | | | 2.00 | | 7.60 | | |
| | | 3 | 5.40 | | | 1.20 | | 19.44 | | |
| | | 1 | 6.00 | | | 2.50 | | 15.00 | | |
| | | 1 | 1.80 | | | 1.40 | | 2.52 | | |
| | | 1 | 3.80 | | | 3.20 | | 12.16 | | |

Assistant Engineer

Assistant Executive Engineer

Assistant Executive Engineer
Nanjangud Sub Division

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| | Kuvempunagara 1st Stage Cross Road | 4 | 3.20 | | | 2.60 | | 33.28 | | |
| | | 1 | 1.50 | | | 1.90 | | 2.85 | | |
| | | 1 | 1.70 | | | 1.60 | | 2.72 | | |
| | | 1 | 1.25 | | | 1.10 | | 1.38 | | |
| | | 1 | 4.50 | | | 0.90 | | 4.05 | | |
| | | 3 | 1.50 | | | 1.60 | | 7.20 | | |
| | | 1 | 2.50 | | | 1.80 | | 4.50 | | |
| | | 1 | 9.00 | | | 1.40 | | 12.60 | | |
| | Kuvempunagara 1st Stage Cross Road | 1 | 6.00 | | | 3.90 | | 23.40 | | |
| | | 1 | 2.20 | | | 1.30 | | 2.86 | | |
| | | 2 | 2.50 | | | 3.90 | | 19.50 | | |
| | | 1 | 1.20 | | | 1.30 | | 1.56 | | |
| | | 1 | 1.10 | | | 1.20 | | 1.32 | | |
| | | 1 | 1.50 | | | 2.10 | | 3.15 | | |
| | | 4 | 4.30 | | | 1.50 | | 25.80 | | |
| | | 1 | 2.20 | | | 1.80 | | 3.96 | | |
| | | 1 | 2.50 | | | 2.00 | | 5.00 | | |
| | Varadarajanagara main Road | 1 | 3.50 | | | 1.40 | | 4.90 | | |
| | | 2 | 4.60 | | | 2.00 | | 18.40 | | |
| | | 1 | 3.50 | | | 1.50 | | 5.25 | | |
| | | 1 | 1.80 | | | 1.40 | | 2.52 | | |
| | | 1 | 2.10 | | | 1.30 | | 2.73 | | |
| | | 2 | 5.00 | | | 4.00 | | 40.00 | | |
| | | 3 | 4.20 | | | 1.50 | | 18.90 | | |
| | 1st Cross Road | 1 | 3.80 | | | 1.00 | | 3.80 | | |
| | | 1 | 3.60 | | | 3.50 | | 12.60 | | |
| | | 1 | 1.60 | | | 3.50 | | 5.60 | | |
| | | 1 | 2.40 | | | 1.30 | | 3.12 | | |
| | | 2 | 1.80 | | | 1.60 | | 5.76 | | |
| | | 2 | 3.50 | | | 1.80 | | 12.60 | | |
| | | 1 | 4.00 | | | 1.80 | | 7.20 | | |
| | 2nd Cross | 1 | 2.10 | | | 4.00 | | 8.40 | | |
| | | 1 | 1.30 | | | 1.25 | | 1.63 | | |
| | | 1 | 5.50 | | | 0.90 | | 4.95 | | |
| | | 4 | 5.50 | | | 0.90 | | 19.80 | | |
| | | 1 | 2.10 | | | 2.00 | | 4.20 | | |
| | | 1 | 1.40 | | | 3.00 | | 4.20 | | |
| | Srinidhi Layout Main Road | 3 | 3.20 | | | 2.20 | | 21.12 | | |
| | | 1 | 3.50 | | | 1.80 | | 6.30 | | |
| | | 1 | 2.20 | | | 2.80 | | 6.16 | | |
| | | 1 | 2.50 | | | 3.90 | | 9.75 | | |
| | | 2 | 4.80 | | | 1.30 | | 12.48 | | |
| | | 1 | 3.20 | | | 2.80 | | 8.96 | | |
| | | 1 | 2.80 | | | 2.10 | | 5.88 | | |
| | | 1 | 4.30 | | | 3.50 | | 15.05 | | |
| | Srinidhi Layout 1st Cross | 2 | 2.20 | | | 1.80 | | 7.92 | | |
| | | 1 | 3.50 | | | 1.70 | | 5.95 | | |
| | | 1 | 2.50 | | | 1.40 | | 3.50 | | |
| | | 1 | 5.50 | | | 0.95 | | 5.23 | | |
| | | 3 | 1.50 | | | 1.50 | | 6.75 | | |
| | | 1 | 6.00 | | | 1.40 | | 8.40 | | |

Assistant Engineer

Assistant Executive Engineer

Assistant Executive Engineer
Vidyaranyapura Sub Division

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| | | 1 | 2.10 | | | 1.30 | | 2.73 | | |
| | | 1 | 2.80 | | | 2.60 | | 7.28 | | |
| | Srinidhi Layout 2nd Cross | 3 | 3.80 | | | 1.90 | | 21.66 | | |
| | | 1 | 9.00 | | | 1.60 | | 14.40 | | |
| | | 1 | 5.00 | | | 1.10 | | 5.50 | | |
| | | 1 | 6.00 | | | 3.00 | | 18.00 | | |
| | | 1 | 2.20 | | | 1.30 | | 2.86 | | |
| | | 2 | 2.50 | | | 3.90 | | 19.50 | | |
| | | 1 | 1.20 | | | 1.30 | | 1.56 | | |
| | | 1 | 5.50 | | | 3.00 | | 16.50 | | |
| | Balaji Layout 1st Cross | 1 | 1.50 | | | 2.10 | | 3.15 | | |
| | | 3 | 4.30 | | | 1.50 | | 19.35 | | |
| | | 1 | 2.20 | | | 1.80 | | 3.96 | | |
| | | 1 | 4.00 | | | 2.50 | | 10.00 | | |
| | Balaji Layout 2nd Cross | 1 | 9.00 | | | 1.40 | | 12.60 | | |
| | | 2 | 1.20 | | | 0.95 | | 2.28 | | |
| | | 1 | 4.80 | | | 3.60 | | 17.28 | | |
| | | 2 | 1.80 | | | 1.40 | | 5.04 | | |
| | Balaji Layout 2nd Cross | 1 | 4.80 | | | 3.20 | | 15.36 | | |
| | | 1 | 4.00 | | | 1.80 | | 7.20 | | |
| | | 2 | 2.50 | | | 3.90 | | 19.50 | | |
| | | 1 | 4.20 | | | 1.30 | | 5.46 | | |
| | | 1 | 3.00 | | | 2.80 | | 8.40 | | |
| | | 1 | 2.80 | | | 2.10 | | 5.88 | | |
| | | 4 | 4.30 | | | 1.50 | | 25.80 | | |
| | | 1 | 3.50 | | | 2.50 | | 8.75 | | |
| | Balaji Layout 3rd Cross | 2 | 3.20 | | | 1.70 | | 10.88 | | |
| | | 1 | 4.20 | | | 3.00 | | 12.60 | | |
| | | 2 | 4.90 | | | 2.00 | | 19.60 | | |
| | | 1 | 2.80 | | | 1.50 | | 4.20 | | |
| | | 1 | 4.80 | | | 1.40 | | 6.72 | | |
| | | 1 | 2.10 | | | 1.30 | | 2.73 | | |
| | | 2 | 3.30 | | | 2.80 | | 18.48 | | |
| | | 1 | 3.00 | | | 1.20 | | 3.60 | | |
| | | | | | | | **Total Qty =** | **1479.33** | | |
| | | | | | | | **Qty Limited to=** | **1477.92** | 328.00 | **484758.00** |
| | | | | | | | | | | |
| 3 | Earthwork excavation by manual means in ordinary soil involving an average horizontal throw upto 2 meters and an average lift upto 0.5 m, excavated surface leveled and sides neatly dressed, the disposed earth to be leveled neatly after breaking of clods complete as per specifications | | | | | | | | Cum | |
| | Singapura Main Road | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 25.00 | | | 0.45 | 0.30 | 6.75 | | |
| | | 2x2 | 30.00 | | | 0.45 | 0.45 | 24.30 | | |
| | | 2 | 29.50 | | | 0.45 | 0.45 | 11.95 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.30 | 24.30 | | |
| | | 2 | 28.60 | | | 0.45 | 0.45 | 11.58 | | |
| | Singapura 1st Cross | 2x4 | 30.00 | | | 0.45 | 0.40 | 43.20 | | |
| | | 2 | 26.20 | | | 0.45 | 0.35 | 8.25 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 25.00 | | | 0.45 | 0.35 | 7.88 | | |
| | | 2x2 | 30.00 | | | 0.45 | 0.40 | 21.60 | | |

Assistant Engineer

Assistant Executive Engineer

Assistant Executive Engineer
Sub Division

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| | | 2 | 25.00 | | | 0.45 | 0.35 | 7.88 | | |
| | | 2x8 | 30.00 | | | 0.45 | 0.40 | 86.40 | | |
| | | 2 | 25.00 | | | 0.45 | 0.35 | 7.88 | | |
| | Singapura 3rd Cross | 2x4 | 30.00 | | | 0.45 | 0.45 | 48.60 | | |
| | | 2 | 21.50 | | | 0.45 | 0.45 | 8.71 | | |
| | | 2x2 | 30.00 | | | 0.45 | 0.35 | 18.90 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.40 | 32.40 | | |
| | | 2 | 16.90 | | | 0.45 | 0.30 | 4.56 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.35 | 28.35 | | |
| | | 2 | 25.00 | | | 0.45 | 0.45 | 10.13 | | |
| | Singapura Layout Main Road | 2x4 | 30.00 | | | 0.45 | 0.45 | 48.60 | | |
| | | 2 | 16.80 | | | 0.45 | 0.35 | 5.29 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.35 | 28.35 | | |
| | | 2 | 31.60 | | | 0.45 | 0.45 | 12.80 | | |
| | | 2x4 | 30.00 | | | 0.45 | 0.40 | 43.20 | | |
| | | 2 | 29.50 | | | 0.45 | 0.45 | 11.95 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.35 | 28.35 | | |
| | | 2 | 24.70 | | | 0.45 | 0.45 | 10.00 | | |
| | Singapura Layout 1st Main | 2x2 | 30.00 | | | 0.45 | 0.35 | 18.90 | | |
| | | 2 | 30.40 | | | 0.45 | 0.45 | 12.31 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.40 | 32.40 | | |
| | | 2 | 25.00 | | | 0.45 | 0.35 | 7.88 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 26.40 | | | 0.45 | 0.40 | 9.50 | | |
| | | 2x5 | 30.00 | | | 0.45 | 0.40 | 54.00 | | |
| | | 2 | 28.00 | | | 0.45 | 0.30 | 7.56 | | |
| | Singapura Layout 1st Main 1st Cross | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 26.00 | | | 0.45 | 0.35 | 8.19 | | |
| | | 2x2 | 30.00 | | | 0.45 | 0.45 | 24.30 | | |
| | | 2 | 30.00 | | | 0.45 | 0.35 | 9.45 | | |
| | | 2x4 | 30.00 | | | 0.45 | 0.35 | 37.80 | | |
| | Varadarajanagara 1st main Road | 2 | 28.00 | | | 0.45 | 0.45 | 11.34 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.30 | 24.30 | | |
| | | 2 | 29.00 | | | 0.45 | 0.45 | 11.75 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 24.00 | | | 0.45 | 0.45 | 9.72 | | |
| | Varadarajanagara 2nd main Road | 2x3 | 30.00 | | | 0.45 | 0.40 | 32.40 | | |
| | | 2 | 29.00 | | | 0.45 | 0.35 | 9.14 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.40 | 32.40 | | |
| | | 2 | 15.00 | | | 0.45 | 0.45 | 6.08 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.35 | 28.35 | | |
| | | 2 | 22.00 | | | 0.45 | 0.45 | 8.91 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | 1st Cross Road | 2 | 18.00 | | | 0.45 | 0.35 | 5.67 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 26.00 | | | 0.45 | 0.40 | 9.36 | | |
| | | 2x4 | 30.00 | | | 0.45 | 0.45 | 48.60 | | |
| | | 2 | 12.80 | | | 0.45 | 0.45 | 5.18 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.35 | 28.35 | | |
| | | 2 | 26.70 | | | 0.45 | 0.45 | 10.81 | | |
| | 2nd Cross | 2x6 | 30.00 | | | 0.45 | 0.45 | 72.90 | | |

Assistant Engineer

Assistant Executive Engineer

Assistant Executive Engineer
Sub Division

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| | | 2 | 22.80 | | | 0.45 | 0.40 | 8.21 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.35 | 28.35 | | |
| | | 2 | 26.80 | | | 0.45 | 0.45 | 10.85 | | |
| | | 2x2 | 30.00 | | | 0.45 | 0.40 | 21.60 | | |
| | | 2 | 18.90 | | | 0.45 | 0.45 | 7.65 | | |
| | Srinidhi Layout Main Road | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 30.20 | | | 0.45 | 0.40 | 10.87 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 26.50 | | | 0.45 | 0.35 | 8.35 | | |
| | | 2x6 | 30.00 | | | 0.45 | 0.45 | 72.90 | | |
| | | 2 | 25.20 | | | 0.45 | 0.30 | 6.80 | | |
| | | 2x4 | 30.00 | | | 0.45 | 0.45 | 48.60 | | |
| | | 2 | 26.80 | | | 0.45 | 0.30 | 7.24 | | |
| | Srinidhi Layout 1st Cross | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 30.00 | | | 0.45 | 0.40 | 10.80 | | |
| | | 2x2 | 30.00 | | | 0.45 | 0.40 | 21.60 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.35 | 28.35 | | |
| | | 2 | 16.90 | | | 0.45 | 0.45 | 6.84 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 25.00 | | | 0.45 | 0.45 | 10.13 | | |
| | | 2x6 | 30.00 | | | 0.45 | 0.30 | 48.60 | | |
| | Srinidhi Layout 2nd Cross | 2 | 16.80 | | | 0.45 | 0.45 | 6.80 | | |
| | | 2x5 | 30.00 | | | 0.45 | 0.40 | 54.00 | | |
| | | 2 | 31.60 | | | 0.45 | 0.45 | 12.80 | | |
| | | 2x4 | 30.00 | | | 0.45 | 0.40 | 43.20 | | |
| | | 2 | 29.50 | | | 0.45 | 0.45 | 11.95 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 22.20 | | | 0.45 | 0.45 | 8.99 | | |
| | | 2x4 | 30.00 | | | 0.45 | 0.40 | 43.20 | | |
| | Balaji Layout 1st Cross | 2 | 12.80 | | | 0.45 | 0.40 | 4.61 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 26.70 | | | 0.45 | 0.45 | 10.81 | | |
| | | 2x2 | 30.00 | | | 0.45 | 0.45 | 24.30 | | |
| | Balaji Layout 2nd Cross | 2 | 22.80 | | | 0.45 | 0.35 | 7.18 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 26.80 | | | 0.45 | 0.40 | 9.65 | | |
| | | 2x5 | 30.00 | | | 0.45 | 0.40 | 54.00 | | |
| | Balaji Layout 2nd Cross | 2 | 18.90 | | | 0.45 | 0.35 | 5.95 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 30.20 | | | 0.45 | 0.45 | 12.23 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.40 | 32.40 | | |
| | | 2 | 26.50 | | | 0.45 | 0.45 | 10.73 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.40 | 32.40 | | |
| | | 2 | 25.20 | | | 0.45 | 0.40 | 9.07 | | |
| | | 2x4 | 30.00 | | | 0.45 | 0.40 | 43.20 | | |
| | Balaji Layout 3rd Cross | 2 | 26.80 | | | 0.45 | 0.40 | 9.65 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.35 | 28.35 | | |
| | | 2 | 26.00 | | | 0.45 | 0.40 | 9.36 | | |
| | | 2x2 | 30.00 | | | 0.45 | 0.45 | 24.30 | | |
| | | 2 | 30.00 | | | 0.45 | 0.40 | 10.80 | | |
| | | 2x4 | 30.00 | | | 0.45 | 0.45 | 48.60 | | |

Assistant Engineer

Assistant Executive Engineer

Assistant Executive Engineer
Kanyapura Sub Division

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| | Balaji Layout 4th Cross | 2 | 28.00 | | | 0.45 | 0.40 | 10.08 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 30.50 | | | 0.45 | 0.45 | 12.35 | | |
| | | 2x3 | 30.00 | | | 0.45 | 0.45 | 36.45 | | |
| | | 2 | 26.80 | | | 0.45 | 0.35 | 8.44 | | |
| | | | | | | | Total Qty = | 2756.50 | | |
| | | | | | | | Qty Limited to= | 2754.45 | 86.00 | 236883.00 |
| | | | | | | | | | | |
| 4 | Earthwork excavation for foundation of buildings, water supply, sanitary lines and electrical conduits either in pits or in trenches 1.5m and above in width, in ordinary soil not exceeding 1.5 m. in depth including dressing the bottom and sides of pits and trenches, stacking the excavated soil clear from edges of excavation with lead upto 50 m. after breaking of clods complete as per specifications | | | | | | | | Cum | |
| | Singapura Main Road | 2x3 | 30.00 | | | 0.90 | 0.25 | 40.50 | | |
| | | 2 | 25.00 | | | 0.95 | 0.20 | 9.50 | | |
| | | 2x2 | 30.00 | | | 0.90 | 0.25 | 27.00 | | |
| | | 2 | 29.50 | | | 1.00 | 0.25 | 14.75 | | |
| | | 2x3 | 30.00 | | | 1.25 | 0.15 | 33.75 | | |
| | | 2 | 28.60 | | | 1.00 | 0.20 | 11.44 | | |
| | Singapura 1st Cross | 2x4 | 30.00 | | | 0.95 | 0.20 | 45.60 | | |
| | | 2 | 26.20 | | | 1.00 | 0.20 | 10.48 | | |
| | | 2x3 | 30.00 | | | 0.90 | 0.20 | 32.40 | | |
| | | 2 | 25.00 | | | 0.90 | 0.25 | 11.25 | | |
| | | 2x2 | 30.00 | | | 1.00 | 0.25 | 30.00 | | |
| | | 2 | 25.00 | | | 1.00 | 0.25 | 12.50 | | |
| | | 2x8 | 30.00 | | | 1.20 | 0.20 | 115.20 | | |
| | | 2 | 25.00 | | | 1.35 | 0.25 | 16.88 | | |
| | Singapura 3rd Cross | 2x4 | 30.00 | | | 1.00 | 0.25 | 60.00 | | |
| | | 2 | 21.50 | | | 1.00 | 0.15 | 6.45 | | |
| | | 2x2 | 30.00 | | | 0.95 | 0.20 | 22.80 | | |
| | | 2x3 | 30.00 | | | 0.90 | 0.25 | 40.50 | | |
| | | 2 | 16.90 | | | 0.80 | 0.20 | 5.41 | | |
| | | 2x3 | 30.00 | | | 1.50 | 0.25 | 67.50 | | |
| | | 2 | 25.00 | | | 1.20 | 0.25 | 15.00 | | |
| | Singapura Layout Main Road | 2x4 | 30.00 | | | 1.00 | 0.30 | 72.00 | | |
| | | 2 | 16.80 | | | 0.95 | 0.30 | 9.58 | | |
| | | 2x3 | 30.00 | | | 1.00 | 0.25 | 45.00 | | |
| | | 2 | 31.60 | | | 1.00 | 0.30 | 18.96 | | |
| | | 2x4 | 30.00 | | | 0.95 | 0.25 | 57.00 | | |
| | | 2 | 29.50 | | | 1.00 | 0.15 | 8.85 | | |
| | | 2x3 | 30.00 | | | 1.00 | 0.20 | 36.00 | | |
| | | 2 | 24.70 | | | 0.95 | 0.30 | 14.08 | | |
| | Singapura Layout 1st Main | 2x2 | 30.00 | | | 1.00 | 0.30 | 36.00 | | |
| | | 2 | 30.40 | | | 0.85 | 0.25 | 12.92 | | |
| | | 2x3 | 30.00 | | | 0.95 | 0.20 | 34.20 | | |
| | | 2 | 25.00 | | | 1.00 | 0.30 | 15.00 | | |
| | | 2x3 | 30.00 | | | 1.00 | 0.20 | 36.00 | | |
| | | 2 | 26.40 | | | 1.20 | 0.25 | 15.84 | | |
| | | 2x5 | 30.00 | | | 1.30 | 0.15 | 58.50 | | |
| | | 2 | 28.00 | | | 1.20 | 0.25 | 16.80 | | |
| | Singapura Layout 1st Main 1st Cross | 2x3 | 30.00 | | | 2.00 | 0.15 | 54.00 | | |
| | | 2 | 26.00 | | | 1.00 | 0.25 | 13.00 | | |

Assistant Engineer

Assistant Executive Engineer

Assistant Executive Engineer
Sub Division

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| | | 2x2 | 30.00 | | | 2.20 | 0.30 | 79.20 | | |
| | | 2 | 30.00 | | | 1.20 | 0.15 | 10.80 | | |
| | | 2x4 | 30.00 | | | 1.20 | 0.20 | 57.60 | | |
| | Varadarajanagara 1st main Road | 2 | 28.00 | | | 1.35 | 0.20 | 15.12 | | |
| | | 2x3 | 30.00 | | | 1.20 | 0.20 | 43.20 | | |
| | | 2 | 29.00 | | | 1.00 | 0.30 | 17.40 | | |
| | | 2x3 | 30.00 | | | 1.00 | 0.25 | 45.00 | | |
| | | 2 | 24.00 | | | 0.95 | 0.25 | 11.40 | | |
| | Varadarajanagara 2nd main Road | 2x3 | 30.00 | | | 0.90 | 0.15 | 24.30 | | |
| | | 2 | 29.00 | | | 1.20 | 0.30 | 20.88 | | |
| | | 2x3 | 30.00 | | | 1.00 | 0.25 | 45.00 | | |
| | | 2 | 15.00 | | | 1.20 | 0.30 | 10.80 | | |
| | | 2x3 | 30.00 | | | 1.35 | 0.15 | 36.45 | | |
| | | 2 | 22.00 | | | 1.20 | 0.25 | 13.20 | | |
| | | 2x3 | 30.00 | | | 1.00 | 0.10 | 18.00 | | |
| | 1st Cross Road | 2 | 18.00 | | | 0.95 | 0.25 | 8.55 | | |
| | | 2x3 | 30.00 | | | 0.85 | 0.30 | 45.90 | | |
| | | 2 | 26.00 | | | 0.90 | 0.25 | 11.70 | | |
| | | 2x4 | 30.00 | | | 1.20 | 0.10 | 28.80 | | |
| | | 2 | 12.80 | | | 1.00 | 0.25 | 6.40 | | |
| | | 2x3 | 30.00 | | | 0.95 | 0.25 | 42.75 | | |
| | | 2 | 26.70 | | | 1.50 | 0.25 | 20.03 | | |
| | 2nd Cross | 2x6 | 30.00 | | | 1.30 | 0.30 | 140.40 | | |
| | | 2 | 22.80 | | | 1.25 | 0.25 | 14.25 | | |
| | | 2x3 | 30.00 | | | 1.00 | 0.20 | 36.00 | | |
| | | 2 | 26.80 | | | 0.95 | 0.20 | 10.18 | | |
| | | 2x2 | 30.00 | | | 1.00 | 0.20 | 24.00 | | |
| | | 2 | 18.90 | | | 1.00 | 0.25 | 9.45 | | |
| | Srinidhi Layout Main Road | 2x3 | 30.00 | | | 1.20 | 0.25 | 54.00 | | |
| | | 2 | 30.20 | | | 1.35 | 0.30 | 24.46 | | |
| | | 2x3 | 30.00 | | | 1.25 | 0.25 | 56.25 | | |
| | | 2 | 26.50 | | | 1.30 | 0.15 | 10.34 | | |
| | | 2x6 | 30.00 | | | 1.25 | 0.25 | 112.50 | | |
| | | 2 | 25.20 | | | 1.30 | 0.25 | 16.38 | | |
| | | 2x4 | 30.00 | | | 1.20 | 0.15 | 43.20 | | |
| | | 2 | 26.80 | | | 1.35 | 0.25 | 18.09 | | |
| | Srinidhi Layout 1st Cross | 2x3 | 30.00 | | | 1.40 | 0.20 | 50.40 | | |
| | | 2 | 30.00 | | | 1.00 | 0.25 | 15.00 | | |
| | | 2x2 | 30.00 | | | 0.95 | 0.20 | 22.80 | | |
| | | 2x3 | 30.00 | | | 1.20 | 0.25 | 54.00 | | |
| | | 2 | 16.90 | | | 0.95 | 0.25 | 8.03 | | |
| | | 2x3 | 30.00 | | | 0.95 | 0.25 | 42.75 | | |
| | | 2 | 25.00 | | | 1.20 | 0.25 | 15.00 | | |
| | | 2x6 | 30.00 | | | 0.85 | 0.20 | 61.20 | | |
| | Srinidhi Layout 2nd Cross | 2 | 16.80 | | | 0.80 | 0.25 | 6.72 | | |
| | | 2x5 | 30.00 | | | 1.20 | 0.20 | 72.00 | | |
| | | 2 | 31.60 | | | 1.00 | 0.25 | 15.80 | | |
| | | 2x4 | 30.00 | | | 0.95 | 0.25 | 57.00 | | |
| | | 2 | 29.50 | | | 0.95 | 0.25 | 14.01 | | |
| | | 2x3 | 30.00 | | | 0.85 | 0.15 | 22.95 | | |
| | | 2 | 22.20 | | | 0.90 | 0.25 | 9.99 | | |

Assistant Engineer

Assistant Executive Engineer

Assistant Executive Engineer
Vidyaranyapur Sub Division

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| | | 2x4 | 30.00 | | | 1.00 | 0.25 | 60.00 | | |
| | Balaji Layout 1st Cross | 2 | 12.80 | | | 1.20 | 0.25 | 7.68 | | |
| | | 2x3 | 30.00 | | | 1.30 | 0.20 | 46.80 | | |
| | | 2 | 26.70 | | | 1.25 | 0.25 | 16.69 | | |
| | | 2x2 | 30.00 | | | 0.95 | 0.20 | 22.80 | | |
| | Balaji Layout 2nd Cross | 2 | 22.80 | | | 0.90 | 0.15 | 6.16 | | |
| | | 2x3 | 30.00 | | | 0.85 | 0.15 | 22.95 | | |
| | | 2 | 26.80 | | | 0.95 | 0.25 | 12.73 | | |
| | | 2x5 | 30.00 | | | 1.25 | 0.20 | 75.00 | | |
| | Balaji Layout 2nd Cross | 2 | 18.90 | | | 1.00 | 0.20 | 7.56 | | |
| | | 2x3 | 30.00 | | | 0.95 | 0.15 | 25.65 | | |
| | | 2 | 30.20 | | | 1.25 | 0.25 | 18.88 | | |
| | | 2x3 | 30.00 | | | 0.90 | 0.25 | 40.50 | | |
| | | 2 | 26.50 | | | 1.20 | 0.20 | 12.72 | | |
| | | 2x3 | 30.00 | | | 0.95 | 0.25 | 42.75 | | |
| | | 2 | 25.20 | | | 0.90 | 0.15 | 6.80 | | |
| | | 2x4 | 30.00 | | | 1.20 | 0.25 | 72.00 | | |
| | Balaji Layout 3rd Cross | 2 | 26.80 | | | 0.90 | 0.25 | 12.06 | | |
| | | 2x3 | 30.00 | | | 0.85 | 0.15 | 22.95 | | |
| | | 2 | 26.00 | | | 0.95 | 0.20 | 9.88 | | |
| | | 2x2 | 30.00 | | | 0.90 | 0.15 | 16.20 | | |
| | | 2 | 30.00 | | | 1.00 | 0.15 | 9.00 | | |
| | | 2x4 | 30.00 | | | 1.20 | 0.20 | 57.60 | | |
| | Balaji Layout 4th Cross | 2 | 28.00 | | | 1.00 | 0.20 | 11.20 | | |
| | | 2x3 | 30.00 | | | 0.95 | 0.25 | 42.75 | | |
| | | 2 | 30.50 | | | 0.90 | 0.25 | 13.73 | | |
| | | 2x3 | 30.00 | | | 0.85 | 0.25 | 38.25 | | |
| | | 2 | 26.80 | | | 0.95 | 0.20 | 10.18 | | |
| | | | | | | | | **Total Qty =** | **3573.72** | |
| | | | | | | | | **Qty Limited to=** | **3564.60** | 200.00 | **712920.00** |
| 5 | Lead for Disposal of Debris shall be payable at carage rates by Mechanical means inlcuding loading and unloading. From 0.00 to 11.90 Km | | | | | | | | Sqm | |
| | | | | | | | | Qty Vide Item No. 3 + 4 | 6319.05 | | |
| | | | | | | | | **Total Qty =** | **6319.05** | 104.00 | **657181.00** |
| 6 | Providing precast slab of 100mm thick including cost of all materials, labour, curing, transportation, loading unloading, etc., complete as per the direction of engineer in charge | | | | | | | | Sqm | |
| | Covering Slab | | | | | | | | | |
| | Singapura Layout 1st Main | 1 | 10.00 | | | | 0.90 | 9.00 | | |
| | | 1 | 16.00 | | | | 0.90 | 14.40 | | |
| | | 1 | 8.00 | | | | 0.90 | 7.20 | | |
| | | 1 | 14.00 | | | | 0.90 | 12.60 | | |
| | | 1 | 12.00 | | | | 0.90 | 10.80 | | |
| | 1st Cross Road | 1 | 5.00 | | | | 0.90 | 4.50 | | |
| | | 1 | 25.00 | | | | 0.90 | 22.50 | | |
| | | 1 | 10.00 | | | | 0.90 | 9.00 | | |
| | | 1 | 15.00 | | | | 0.90 | 13.50 | | |
| | 2nd Cross | 1 | 10.00 | | | | 0.90 | 9.00 | | |
| | | 1 | 25.00 | | | | 0.90 | 22.50 | | |
| | | 1 | 16.00 | | | | 0.90 | 14.40 | | |

Assistant Engineer

Assistant Executive Engineer

Assistant Executive Engineer
Vidyaranyapura Sub Division

| Sl. No | Description | No. | L | B1 | B2 | Av. B | D | Qty | Rate | Amount |
|---|---|---|---|---|---|---|---|---|---|---|
| | Vinayakanagara 1st Cross | 1 | 18.00 | | | | 0.90 | 16.20 | | |
| | | 1 | 22.00 | | | | 0.90 | 19.80 | | |
| | | 1 | 25.00 | | | | 0.90 | 22.50 | | |
| | | 1 | 18.00 | | | | 0.90 | 16.20 | | |
| | Varadarajanagara 1st Cross | 1 | 17.00 | | | | 0.90 | 15.30 | | |
| | | 1 | 19.00 | | | | 0.90 | 17.10 | | |
| | | 1 | 16.00 | | | | 0.90 | 14.40 | | |
| | 2nd Cross | 1 | 18.00 | | | | 0.90 | 16.20 | | |
| | | 1 | 22.00 | | | | 0.90 | 19.80 | | |
| | | | | | | | **Total Qty =** | **306.90** | | |
| | | | | | | | **Qty Limited to=** | **306.00** | 1600.00 | **489600.00** |
| | | | | | | | | | | |
| | | | | | | | | | **Total** | **2913496.00** |
| **Rupees Twenty Nine Lakh(s) Thirteen Thousand Four Hundred Ninety Six Only** | | | | | | | | | | |

Assistant Engineer
Ward No. 11

Assistant Executive Engineer
Vidayranyapura Sub Division

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97